





<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: EW-5 (Police Station)</p> <p>Orientation: Northerly</p> <p>Subject: On Maple Looking Toward EW-5 location.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: On Maple looking Easterly Toward Halsey Avenue.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: N/A</p> <p>Subject: Looking at proposed lay-down area.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: N/A</p> <p>Subject: Pole in parking lot with telephone wiring from previous phase of work.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: Westerly</p> <p>Subject: Lay-Down Area Parking Lot showing asphalt condition.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location:</p> <p>Orientation: N/A</p> <p>Subject: Sign indicating former location of the Morris Canal.</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Jackson Avenue</p> <p>Orientation: N/A</p> <p>Subject: Former Proposed Location for the Treatment Plant.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Jackson Avenue</p> <p>Orientation: N/A</p> <p>Subject: Former Proposed Location for the Treatment Plant.</p>	




<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Halsey Avenue</p> <p>Orientation: Northerly</p> <p>Subject: Proposed location for EW-6.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Halsey Avenue</p> <p>Orientation: Northerly</p> <p>Subject: Proposed location for EW-6.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Halsey Avenue</p> <p>Orientation: Northerly</p> <p>Subject: View of Halsey Avenue in area of Proposed EW-6.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: EW-7; Park Area</p> <p>Orientation: Northeasterly</p> <p>Subject: View of Playground Area.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: EW-7; Park Area</p> <p>Orientation: Northerly</p> <p>Subject: View from Maple Avenue at proposed access area.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: EW-7 Park Area</p> <p>Orientation: Easterly</p> <p>Subject: View of fencing along Maple Avenue.</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: View looking east from center of Maple Avenue.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Intersection of Maple & Halsey.</p> <p>Orientation: Easterly</p> <p>Subject: View from center of Maple Avenue & Halsey looking Easterly.</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: EW-6 Halsey Avenue</p> <p>Orientation: Northerly</p> <p>Subject: View of Halsey Area from Maple Avenue looking Northerly.</p>



<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Intersection of Halsey & Jackson</p> <p>Orientation: Easterly</p> <p>Subject: Looking east on Jackson from Halsey.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: N/A</p> <p>Subject: Electrical Pole in parking lot.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Toward Soccer Field</p> <p>Subject: Northeast curbing of Parking Lot</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Looking Westerly</p> <p>Subject: Parking Lot (Proposed lay-down area)</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Looking Toward Creek</p> <p>Subject: Parking Lot (Proposed lay-down area)</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Looking Toward Creek</p> <p>Subject: Parking Lot (Proposed lay-down area)</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Looking Southeast</p> <p>Subject: Parking Lot (Proposed lay-down area)</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Northeasterly</p> <p>Subject: Near creek looking northeast</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Northerly</p> <p>Subject: Near creek looking Northerly</p>



<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: Northeasterly</p> <p>Subject: Looking at parking lot from other side of creek.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: Northerly</p> <p>Subject: Looking at parking lot from other side of creek.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Westerly</p> <p>Subject: From Police Station looking westerly.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Westerly</p> <p>Subject: From Police Station Looking Westerly.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: From Police Station looking easterly.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: From Police Station looking easterly.</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Maple Ave looking toward Police Station and Park.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: On Maple Avenue, showing condition of Asphalt.</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Showing condition of asphalt where Police driveway exits onto Maple.</p>




<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Police Station Parking Lot</p> <p>Orientation: Easterly</p> <p>Subject: View of Condition of Asphalt in Police Parking Lot.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue at Eastern End of Police Station.</p> <p>Orientation: Easterly</p> <p>Subject: Showing condition of asphalt roadway.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue adjacent to Park.</p> <p>Orientation: Easterly</p> <p>Subject: Showing condition of chain-link fencing.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Showing bend in roadway.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: Westerly</p> <p>Subject: Proposed EW-5 Location</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: Southwesterly</p> <p>Subject: Proposed EW-5 Location</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: N/A</p> <p>Subject: Showing water shut-off valve located in parking lot west of building.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: Easterly</p> <p>Subject: Garage door located on western side of building.</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: West Side of Police Station.</p> <p>Orientation: Northerly</p> <p>Subject: Garage door for Police Station.</p>



<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: N/A</p> <p>Subject: Location of existing Extraction Well, EW-2</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: N/A</p> <p>Subject: View of flush-mount casing for extraction well EW-2.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Police Parking Lot</p> <p>Orientation: South</p> <p>Subject: Looking from proposed EW-5 toward Maple Avenue.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Location of Proposed EW-5</p> <p>Orientation: Westerly</p> <p>Subject: Looking at area for proposed EW-5.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: N/A</p> <p>Subject: Showing anchoring of utility pole guide wires.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: N/A</p> <p>Subject: Photo of sewer manhole on the proposed treatment plant site.</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Northerly</p> <p>Subject: View along Union Avenue in area of proposed treatment plant.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Northerly</p> <p>Subject: View of existing pump house adjacent to proposed treatment plant.</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Easterly</p> <p>Subject: View of rail road embankment running behind treatment plant.</p>



<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Northerly</p> <p>Subject: Location of Treatment Plant south of Pump House.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Northerly</p> <p>Subject: Treatment Plant Area looking north down Union Avenue.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Northeasterly</p> <p>Subject: Treatment Plant Area looking down tracks.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Easterly</p> <p>Subject: Looking at proposed Treatment Plant area from across Union Avenue.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Easterly</p> <p>Subject: Looking at proposed Treatment Plant area from across Union Avenue.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Easterly</p> <p>Subject: Looking at storm sewer inlet and potable water hook-up at TP location.</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Southerly</p> <p>Subject: Looking south at road crossing tracks.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Easterly</p> <p>Subject: Close-up of potable water hook-up valve in front of Treatment Plant.</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area</p> <p>Orientation: Easterly</p> <p>Subject: Rear area of treatment plant showing railroad embankment.</p>



<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant</p> <p>Orientation: N/A</p> <p>Subject: Showing condition of existing pump house building.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: N/A</p> <p>Subject: Showing condition of existing pump house building.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: Northeasterly</p> <p>Subject: Rear of pump house along track embankment.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: Northeasterly</p> <p>Subject: Rear of pump house along track embankment.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: N/A</p> <p>Subject: Back of pump house building.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: Northerly</p> <p>Subject: Area behind pump house.</p>
<p>Photo # 7</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: Northerly</p> <p>Subject: Space behind pump house for treatment plant.</p>	<p>Photo # 8</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: Northeasterly</p> <p>Subject: Space behind pump house for treatment plant.</p>	<p>Photo # 9</p> <p>Date: 4/9/07</p> <p>Location: : Treatment Plant</p> <p>Orientation: Southwesterly</p> <p>Subject: Space behind pump house for treatment plant.</p>



<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Looking east down Maple Avenue in direction of trench.</p>	<p>Photo # 2</p> <p>Date:4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Following path of proposed trench.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Maple Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Following path of proposed trench.</p>
<p>Photo # 4</p> <p>Date:4/9/07</p> <p>Location: Police Station</p> <p>Orientation: Northwesterly</p> <p>Subject: Parking Spot where EW-5 is proposed to be installed.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Police Station</p> <p>Orientation: Northerly</p> <p>Subject: Parking Spot where EW-5 is proposed to be installed.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Police Station</p> <p>Orientation: Westerly</p> <p>Subject: Parking Spot where EW-5 is proposed to be installed.</p>
<p>Photo # 7</p> <p>Date: 5/18/07</p> <p>Location: Property West of Police Station.</p> <p>Orientation: N/A</p> <p>Subject: Area where rig tender to set up during drilling.</p>	<p>Photo # 8</p> <p>Date: 5/18/07</p> <p>Location: Property West of Police Station.</p> <p>Orientation: N/A</p> <p>Subject: Existing grate that will be driven over with drill rig tender.</p>	<p>Photo # 9</p> <p>Date: 5/18/07</p> <p>Location: Maple Avenue – Police Station driveway.</p> <p>Orientation: Easterly</p> <p>Subject: Showing condition of asphalt in Police Station Driveway.</p>




<p>Photo # 1</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area.</p> <p>Orientation: N/A</p> <p>Subject: View showing available space for treatment plant building.</p>	<p>Photo # 2</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area.</p> <p>Orientation:</p> <p>Subject: View showing available space for treatment plant building.</p>	<p>Photo # 3</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area.</p> <p>Orientation:</p> <p>Subject: View showing available space for treatment plant building.</p>
<p>Photo # 4</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area.</p> <p>Orientation: N/A</p> <p>Subject: View of rail track embankment.</p>	<p>Photo # 5</p> <p>Date: 4/9/07</p> <p>Location: Treatment Plant Area.</p> <p>Orientation: Northerly</p> <p>Subject: Rear of pump house showing electrical in area.</p>	<p>Photo # 6</p> <p>Date: 4/9/07</p> <p>Location: Original Proposed Location for Treatment Plant.</p> <p>Orientation: Westerly</p> <p>Subject: Parking lot originally proposed for treatment plant.</p>
<p>Photo # 7</p> <p>Date: 5/18/07</p> <p>Location: Property West of Police Station.</p> <p>Orientation: Northeasterly</p> <p>Subject: Area rig tender to set up during drilling</p>	<p>Photo # 8</p> <p>Date: 5/18/07</p> <p>Location: Property West of Police Station.</p> <p>Orientation: Southerly</p> <p>Subject: Driveway leading to rear of property.</p>	<p>Photo # 9</p> <p>Date: 5/18/07</p> <p>Location: Property West of Police Station.</p> <p>Orientation: N/A</p> <p>Subject: Existing grate that will be driven over with drill rig tender.</p>



<p>Photo # 1</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot</p> <p>Orientation: Westerly</p> <p>Subject: Crew drilling pilot boring EW-5</p>	<p>Photo # 2</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot</p> <p>Orientation: N/A</p> <p>Subject: EW-5 area secured after pilot borehole completion</p>	<p>Photo # 3</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot Orientation: N/A</p> <p>Subject: EW-5 area secured after pilot borehole completion</p>
<p>Photo # 4</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot</p> <p>Orientation: N/A</p> <p>Subject: EW-5 location looking from other side of rock wall.</p>	<p>Photo # 5</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot Orientation: N/A</p> <p>Subject: Condition of Parking Lot prior to Drilling Operations.</p>	<p>Photo # 6</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot Orientation: Northerly</p> <p>Subject: Setting up Rig to perform soil boring.</p>
<p>Photo # 7</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot</p> <p>Orientation: Northerly</p> <p>Subject: Setting up Rig to perform soil boring.</p>	<p>Photo # 8</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot</p> <p>Orientation: Southerly</p> <p>Subject: Setting up Rig to perform soil boring.</p>	<p>Photo # 9</p> <p>Date: 8/23/07</p> <p>Location: Lay-Down Area Parking Lot</p> <p>Orientation: Southerly</p> <p>Subject: Rig set up with mast up.</p>




Photo # 1 Date: 8/23/07 Location: Lay-Down Area Parking Lot Orientation: Southerly Subject: Mast up showing distance from power lines.	Photo # 2 Date: 8/23/07 Location: Lay-Down Area Parking Lot Orientation: Northerly Subject: Setting up Rig for drilling.	Photo # 3 Date: 8/23/07 Location: Lay-Down Area Parking Lot Orientation: Northerly Subject: Setting up rig for drilling.
Photo # 4 Date: 8/23/07 Location: Lay-Down Area Parking Lot Orientation: Northerly Subject: Setting up rig for drilling.	Photo # 5 Date: 8/23/07 Location: Lay-Down Area Parking Lot Orientation: Northerly Subject: Securing rig/area for overnight.	Photo # 6 Date: 8/23/07 Location: Lay-Down Area Parking Lot Orientation: Southerly Subject: Securing area for traffic control.






<p>Photo # 1</p> <p>Date: 8/28/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo of picnic bench with concrete base to be removed.</p>	<p>Photo # 2</p> <p>Date: 8/30/07</p> <p>Location: EW-7</p> <p>Orientation: North</p> <p>Subject: Setting up security fencing at park area (EW-7).</p>	<p>Photo # 3</p> <p>Date: 8/30/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Setting up drilling bit and casing to install at EW-7.</p>
<p>Photo # 4</p> <p>Date: 8/30/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Outer protective casing installed at EW-7.</p>	<p>Photo # 5</p> <p>Date: 8/30/07</p> <p>Location: EW-7</p> <p>Orientation: North</p> <p>Subject: Site secured for off-hours</p>	<p>Photo # 6</p> <p>Date: 9/4/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo of stainless-steel screen and sump for EW-7.</p>
<p>Photo # 7</p> <p>Date: 9/4/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Confirmation on bag of gravel pack indicating correct grade.</p>	<p>Photo # 8</p> <p>Date: 9/4/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Cleaning of interior of 4,000-gallon poly tank discharge.</p>	<p>Photo # 9</p> <p>Date: 8/30/07</p> <p>Location: EW-7</p> <p>Orientation: Easterly</p> <p>Subject: Installing a second length of drilling rod at EW-7.</p>



<p>Photo # 1</p> <p>Date: 9/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Driller welding screen and sump to length of casing.</p>	<p>Photo # 2</p> <p>Date: 9/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Drilling crew placing gravel pack around well screen at EW-7.</p>	<p>Photo # 3</p> <p>Date: 9/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo showing how discharge hose secured to roll-off container.</p>
<p>Photo # 4</p> <p>Date: 9/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Installation of drilling rods and casing continues.</p>	<p>Photo # 5</p> <p>Date: 9/6/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Driller welding two lengths of casing together down borehole.</p>	<p>Photo # 6</p> <p>Date: 9/6/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Cement/bentonite grout mixture being tremie grouted into borehole.</p>
<p>Photo # 7</p> <p>Date: 9/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo of well screen, sump and casing ready to be installed in borehole.</p>	<p>Photo # 8</p> <p>Date: 9/4/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo of interior of 4,000-gallon poly tank after cleaning.</p>	<p>Photo # 9</p> <p>Date: 9/6/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: N/A</p> <p>Subject: Drilling crew measuring depth of gravel pack placed around EW-7 screen.</p>




<p>Photo # 1</p> <p>Date: 8/15/07</p> <p>Location: EW-7</p> <p>Orientation: Northerly</p> <p>Subject: Photo showing electrical lines moved by JCP&L for drill rig access.</p>	<p>Photo # 2</p> <p>Date: 8/15/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: View of tear in roll off side wall that caused box to be rejected.</p>	<p>Photo # 3</p> <p>Date: 8/17/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Driller hand auguring to five feet for utility clearance.</p>
<p>Photo # 4</p> <p>Date: 8/17/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: South</p> <p>Subject: View showing drill rig in relation to overhead wires.</p>	<p>Photo # 5</p> <p>Date: 8/17/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: North</p> <p>Subject: View of work area from Maple Avenue.</p>	<p>Photo # 6</p> <p>Date: 8/17/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: South</p> <p>Subject: View showing drilling bit and 16" casing preparing to drill.</p>
<p>Photo # 7</p> <p>Date: 8/20/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: South</p> <p>Subject: Sliding a second 20-foot section of 16" casing onto drill head.</p>	<p>Photo # 8</p> <p>Date: 8/22/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: South</p> <p>Subject: Drilling EW-7.</p>	<p>Photo # 9</p> <p>Date: 8/22/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Close-up view of dill bit.</p>



<p>Photo # 1</p> <p>Date: 8/23/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Drill cuttings and formation water being discharged into the roll off container.</p>	<p>Photo # 2</p> <p>Date: 8/24/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Photo of stainless steel well screen.</p>	<p>Photo # 3</p> <p>Date: 8/24/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Crew screwing the two section of flush-joint well casing together.</p>
<p>Photo # 4</p> <p>Date: 8/22/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Confirmation photo indicating the gravel pack size is #00.</p>	<p>Photo # 5</p> <p>Date: 8/22/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: Easterly</p> <p>Subject: Confirmation photo indicating the gravel pack size is #2.</p>	<p>Photo # 6</p> <p>Date: 8/23/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: Photo showing screen section being measured to slot size 0.040.</p>
<p>Photo # 7</p> <p>Date: 8/22/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: Southerly</p> <p>Subject: Photo of drilling operations air lifting soil cuttings from borehole.</p>	<p>Photo # 8</p> <p>Date: 8/22/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: Southerly</p> <p>Subject: View of crew taking 20' section of casing off rig tender with hoist.</p>	<p>Photo # 9</p> <p>Date: 8/23/07</p> <p>Location: EW-7, Halsey Avenue</p> <p>Orientation: N/A</p> <p>Subject: View of on of the welded casing joints.</p>



<p>Photo # 1</p> <p>Date: 5/17/07</p> <p>Location: EW-5 Pilot Boring</p> <p>Orientation: Westerly</p> <p>Subject: Crew drilling pilot boring EW-5</p>	<p>Photo # 2</p> <p>Date: 5/17/07</p> <p>Location: EW-5 Pilot Boring</p> <p>Orientation: N/A</p> <p>Subject: EW-5 area secured after pilot borehole completion</p>	<p>Photo # 3</p> <p>Date: 5/17/07</p> <p>Location: EW-5 Pilot Boring</p> <p>Orientation: N/A</p> <p>Subject: EW-5 area secured after pilot borehole completion</p>
<p>Photo # 4</p> <p>Date: 5/17/07</p> <p>Location: EW-5 Pilot Boring</p> <p>Orientation: N/A</p> <p>Subject: EW-5 location looking from other side of rock wall.</p>	<p>Photo # 5</p> <p>Date: 5/17/07</p> <p>Location: EW-5 (Police Parking Lot)</p> <p>Orientation: N/A</p> <p>Subject: Condition of Parking Lot prior to Drilling Operations.</p>	<p>Photo # 6</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Northerly</p> <p>Subject: Setting up Rig to perform soil boring.</p>
<p>Photo # 7</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Northerly</p> <p>Subject: Setting up Rig to perform soil boring.</p>	<p>Photo # 8</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Southerly</p> <p>Subject: Setting up Rig to perform soil boring.</p>	<p>Photo # 9</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Southerly</p> <p>Subject: Rig set up with mast up.</p>




<p>Photo # 1</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Southerly</p> <p>Subject: Mast up showing distance from power lines.</p>	<p>Photo # 2</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Northerly</p> <p>Subject: Setting up Rig for drilling.</p>	<p>Photo # 3</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Northerly</p> <p>Subject: Setting up rig for drilling.</p>
<p>Photo # 4</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Northerly</p> <p>Subject: Setting up rig for drilling.</p>	<p>Photo # 5</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Northerly</p> <p>Subject: Securing rig/area for overnight.</p>	<p>Photo # 6</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Southerly</p> <p>Subject: Securing area for traffic control.</p>
<p>Photo # 7</p> <p>Date: 5/17/07</p> <p>Location: EW-6 (Halsey Avenue)</p> <p>Orientation: Southerly</p> <p>Subject: Securing rig/area for traffic.</p>	<p>Photo # 8</p> <p>Date: 5/18/07</p> <p>Location: EW-7 (Park Area)</p> <p>Orientation: Southerly</p> <p>Subject: Secures soil boring area awaiting installation of extraction well.</p>	<p>Photo # 9</p> <p>Date: 5/11/07</p> <p>Location: EW-7 (Park Area)</p> <p>Orientation: Easterly</p> <p>Subject: Secure drilling rig within park area</p>



<p>Photo # 1</p> <p>Date: 5/11/07</p> <p>Location: EW-7 (Park Area)</p> <p>Orientation: Southerly</p> <p>Subject: Drilling EW-7 Soil Boring.</p>	<p>Photo # 2</p> <p>Date: 5/11/07</p> <p>Location: EW-7 (Park Area)</p> <p>Orientation: Northerly</p> <p>Subject: Soil Boring area awaiting Extraction well installation.</p>	<p>Photo # 3</p> <p>Date: 5/17/07</p> <p>Location: EW-7 (Park Area)</p> <p>Orientation: N/A</p> <p>Subject: Ground Surface at completion of soil boring installation.</p>
<p>Photo # 4</p> <p>Date: 5/17/07</p> <p>Location: EW-7 (Park Area)</p> <p>Orientation: Easterly</p> <p>Subject: Soil Boring area awaiting Extraction well installation.</p>	<p>Photo # 5</p> <p>Date: 5/30/07</p> <p>Location: Lay –Down Area</p> <p>Orientation: Easterly</p> <p>Subject: Lay Down Area</p>	<p>Photo # 6</p> <p>Date: 5/30/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: Southerly</p> <p>Subject: Electrical Panel at Lay Down area awaiting installation of meter.</p>
<p>Photo # 7</p> <p>Date: 5/30/07</p> <p>Location: Lay-Down Area</p> <p>Orientation: Easterly</p> <p>Subject: Lay Down area showing USACE/USEPA Trailer.</p>		



<p>Photo # 1</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Easterly</p> <p>Subject: Rig Tender setting up on neighboring property.</p>	<p>Photo # 2</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Northwesterly</p> <p>Subject: View of both drill rig and rig tender at work.</p>	<p>Photo # 3</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Northerly</p> <p>Subject: View of both drill rig and rig tender at work.</p>
<p>Photo # 4</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Northwesterly</p> <p>Subject: View of both drill rig and rig tender at work.</p>	<p>Photo # 5</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: N/A</p> <p>Subject: Drilling pilot borehole EW-5.</p>	<p>Photo # 6</p> <p>Date: 5/21/07</p> <p>Location: Ew-5; Police Station</p> <p>Orientation: N/A</p> <p>Subject: Drilling pilot borehole EW-5.</p>
<p>Photo # 7</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Westerly</p> <p>Subject: Drilling pilot borehole EW-5.</p>	<p>Photo # 8</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Westerly</p> <p>Subject: EW-5 soil boring casing left in ground from dual rotary rig drilling.</p>	<p>Photo # 9</p> <p>Date: 5/21/07</p> <p>Location: EW-5; Police Station</p> <p>Orientation: Easterly</p> <p>Subject: Neighboring property after completion of soil boring EW-5.</p>



<p>Photo # 1</p> <p>Date: 10/4/07</p> <p>Location: EW-5</p> <p>Orientation: South</p> <p>Subject: Photo of Proof of Process set-up at EW-5.</p>	<p>Photo # 2</p> <p>Date: 10/4/07</p> <p>Location: EW-5</p> <p>Orientation: Easterly</p> <p>Subject: Groundwater sampling during Proof of Process Activities (EW-5).</p>	<p>Photo # 3</p> <p>Date: 10/5/07</p> <p>Location: EW-7</p> <p>Orientation: Northerly</p> <p>Subject: Treatment unit and pump set-up for Proof of Process at EW-7.</p>
<p>Photo # 4</p> <p>Date: 10/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo of canister filter cartridges containing heavy sediment at EW-7.</p>	<p>Photo # 5</p> <p>Date: 10/9/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Treated groundwater being discharged into Frac Tank at EW-7.</p>	<p>Photo # 6</p> <p>Date: 10/5/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Sampling of Treated Groundwater at EW-7.</p>
<p>Photo # 7</p> <p>Date: 10/16/07</p> <p>Location: EW-5</p> <p>Orientation: Easterly</p> <p>Subject: Removing pump and stilling tube from EW-5.</p>	<p>Photo # 8</p> <p>Date: 10/17/07</p> <p>Location: Lay-Down Yard</p> <p>Orientation: Northwesterly</p> <p>Subject: Labor crew emptying drums of soil cuttings from pilot borings into rolloff.</p>	<p>Photo # 9</p> <p>Date: 10/17/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Photo showing pumps electrical controls with grounding rod in place.</p>



<p>Photo # 1</p> <p>Date: 10/17/07</p> <p>Location: EW-7</p> <p>Orientation: Northeasterly/A</p> <p>Subject: Vac truck operator discharging treated groundwater into frac tank.</p>	<p>Photo # 2</p> <p>Date: 10/17/07</p> <p>Location: EW-7</p> <p>Orientation: Northerly</p> <p>Subject: Manually monitoring water levels to confirm transducer readings.</p>	<p>Photo # 3</p> <p>Date: 10/19/07</p> <p>Location: EW-7</p> <p>Orientation: Northerly</p> <p>Subject: Drums available during change out of filter bags during pumping of EW-7.</p>
<p>Photo # 4</p> <p>Date: 10/19/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Set up at EW-7 with control box in plastic during inclement weather.</p>	<p>Photo # 5</p> <p>Date: 10/12/07</p> <p>Location: EW-5</p> <p>Orientation: N/A</p> <p>Subject: Treated water being discharged into storm drain at 25 gpm.</p>	<p>Photo # 6</p> <p>Date: 10/16/07</p> <p>Location: EW-5</p> <p>Orientation: N/A</p> <p>Subject: Set up at EW-5 during pumping test.</p>
<p>Photo # 7</p> <p>Date: 10/17/07</p> <p>Location: EW-7</p> <p>Orientation: N/A</p> <p>Subject: Set up at EW-7 during pumping test.</p>	<p>Photo # 8</p> <p>Date: 10/17/07</p> <p>Location: EW-7</p> <p>Orientation: Northerly</p> <p>Subject: Manually monitoring water levels to confirm transducer readings.</p>	<p>Photo # 9</p> <p>Date: 10/19/07</p> <p>Location: EW-7</p> <p>Orientation: Northwesternly</p> <p>Subject: Mobile groundwater treatment unit...</p>



<p>Photo # 1</p> <p>Date: 9/10/07</p> <p>Location: EW-7</p> <p>Orientation: North</p> <p>Subject: Photo of completed EW-7 well, including protective casing.</p>	<p>Photo # 2</p> <p>Date: 9/11/07</p> <p>Location: EW-5</p> <p>Orientation: Easterly</p> <p>Subject: Area of rock wall moved to allow access for well installation (EW-5).</p>	<p>Photo # 3</p> <p>Date: 9/11/07</p> <p>Location: EW-5</p> <p>Orientation: N/A</p> <p>Subject: Crew pulling 6" casing installed during pilot boring installation..</p>
<p>Photo # 4</p> <p>Date: 9/11/07</p> <p>Location: EW-5</p> <p>Orientation: N/A</p> <p>Subject: Outer protective casing with cutting shoe installed at EW-5.</p>	<p>Photo # 5</p> <p>Date: 9/12/07</p> <p>Location: EW-5</p> <p>Orientation: North</p> <p>Subject: Combining drilling rod, bit and outer casing for installation.</p>	<p>Photo # 6</p> <p>Date: 9/13/07</p> <p>Location: EW-5</p> <p>Orientation: Easterly</p> <p>Subject: Driller welding casing sections, with the use of a welding shield..</p>
<p>Photo # 7</p> <p>Date: 9/14/07</p> <p>Location: EW-7A</p> <p>Orientation: Easterly</p> <p>Subject: Obtaining approval for EW-7A location with Borough Superintendent.</p>	<p>Photo # 8</p> <p>Date: 9/17/07</p> <p>Location: EW-5</p> <p>Orientation: Northeasterly</p> <p>Subject: Installation of well screen, sump and casing at EW-5.</p>	<p>Photo # 9</p> <p>Date: 9/17/07</p> <p>Location: EW-5</p> <p>Orientation: N/A</p> <p>Subject: Installing a sand (gravel) pack at EW-5.</p>



<p>Photo # 1</p> <p>Date: 9/24/07</p> <p>Location: EW-5</p> <p>Orientation: N/A</p> <p>Subject: Photo of completed EW-5 well, including protective casing..</p>	<p>Photo # 2</p> <p>Date: 9/24/07</p> <p>Location: EW-5</p> <p>Orientation: Easterly</p> <p>Subject: Photo of rebuilt rock wall between police station and 21 Maple Avenue.</p>	<p>Photo # 3</p> <p>Date: 9/24/07</p> <p>Location: EW-5</p> <p>Orientation: Easterly</p> <p>Subject: Photo of rebuilt rock wall between police station and 21 Maple Avenue.</p>
<p>Photo # 4</p> <p>Date: 9/24/07</p> <p>Location: EW-7A</p> <p>Orientation: N/A</p> <p>Subject: Confirming EW-7A well screen slot size prior to installation..</p>	<p>Photo # 5</p> <p>Date: 9/24/07</p> <p>Location: EW-7A</p> <p>Orientation: Easterly</p> <p>Subject: Driller crew setting up discharge hose for drilling EW-7A.</p>	<p>Photo # 6</p> <p>Date: 9/26/07</p> <p>Location: EW-7A</p> <p>Orientation: N/A</p> <p>Subject: Development water from EW-7A development.</p>
<p>Photo # 7</p> <p>Date: 9/26/07</p> <p>Location: Mount Hope Quarry</p> <p>Orientation: N/A</p> <p>Subject: Sample technician collecting backfill material for analysis.</p>	<p>Photo # 8</p> <p>Date: 9/26/07</p> <p>Location: Belle Mead Quarry</p> <p>Orientation: N/A</p> <p>Subject: Sample technician collecting Topsoil material for analysis..</p>	<p>Photo # 9</p> <p>Date: 9/25/07</p> <p>Location: EW-7A</p> <p>Orientation: Easterly</p> <p>Subject: Drilling crew removing rods and casings at EW-7A.</p>

